

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 104 Const Calendar Day: 303 Date: 08-Jul-2010 Thursday

Inspector Name: Daouk, Sami Title:

Inspection Type: Continuous

Shift Hours: 07:00 am 05:30 pm **Break:** 00:30 **Over Time:** 02:00

Federal ID: Location:

Reviewer: Wright, Doug Approved Date: 12-Jul-10 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Sunny

Working Day | If no, explain:

Diary:

Tower Activities

ABF crews came to the site at 6:50 AM. Crews had to work on the preparations for the tower erection on the top of the footing box . They started at 7:00 AM.

Carlos G. & Carlos M. had to work on the touch ups. Crews had to sand blast few locations for the 2nd time. They had to prepare the sand blasting machine & hoses, & blast the missed locations. Crews started at 7:10 AM. They were done at 8:30 AM.

After that , crews had to disassemble the hoses , blasting machine , wrap up tools & equipment . Crews were done at 11:30 AM.

Jose & Rick had to clean the top of the footing box. Crews had to vacuum the sand, remove the plywood boards, & pile them on the site to be hauled out of the site. They started at 7:15 AM. Crews were done at 11:30 AM.

Then , crews had to form around the perimeter of the kidneys & the perimeter of the jacking areas . Crews started had to form around the South East kidney at 11:35 AM. They had to place prefabricated side panels of 0.1 meter high , 2.5 meters long , cut to size & angle , set in place & secure them with anchor nails . Crews were done on the South East kidney at 1:15 PM.

Following the same procedures as on the South East kidney form work . Crews were done on the North East kidney at 2:20 PM

after that , crews had to form around the 14 jacks locations . They started at 2:15 PM. to form around the East side jacking locations . Crews stopped at 3:30 PM. to work on the shims placement . Crews were done at 5:10 PM. They had to wrap up their tools & equipment. Crews left at 5:20 PM.

ABF surveyors came to the site at 11:00 AM. They had to mark the additional required shim thicknesses on the top of each of the existing shims. Crews were done at 1:30 PM.

Aaron , Augie , Barry , & Kevin came to the site at 1:30 PM. Crews had to work on placing the additional shims on each of the existing shims according to the surveyor numbers . Crews had to sort the shims according to the thickness & size . They started at 1:45 PM. They were done at 3:15 PM. Crews left at 3:20 PM.

| 04-0120F4 | Bid Item: 05 | 3 T-L01-JSS.053 | Tower Lift 01 Jacking System and Shims | |
|---------------|-----------------|-----------------|--|---------|
| AMERICAN BRID | OGE/FLUOR, A JV | | | |
| Labor | | | | |
| Trade | Class | Name | RT Hrs OT Hrs DT Hrs Total Remarks | Dispute |
| Contractor: | AMERICAN BRIDGE | FLUOR, A JV | | |
| Ironworker | JNM | KEVIN RATCLIFF | 2.00 0.00 0.00 2.00 | |
| Ironworker | JNM | BARRY ROTHMAN | 2.00 0.00 0.00 2.00 | |
| | | | | |



Run date 21-Nov-14

3:11 PM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

| c, Sami Diary #: 104 Date: 08-Jul-2010 Thursday | ector Name Daouk, Sami | Name: 04-0120F4 |
|---|------------------------|-------------------------|
| 2.00 0.00 0.00 2.00 | AUGIE SOLIS 2.0 | Ironworker A |
| 2.00 0.00 0.00 2.00 | AARON KENT 2.0 | Ironworker F |
| NO 8.00 2.00 0.00 10.00 | CARLOS MONTEJANO 8.0 | Semi-Skilled Laborer JI |
| OS 8.00 2.00 0.00 10.00 | RIGOBERTO CAMPOS 8.0 | Semi-Skilled Laborer JI |
| 8.00 2.00 0.00 10.00 | JOSE ROMO 8.0 | Semi-Skilled Laborer A |
| 8.00 2.00 0.00 10.00 | CARLOS GARCIA 8.0 | Semi-Skilled Laborer JI |
| Rental Company | | ipment |
| RT Hrs OT Hrs ST Hrs IT Hrs Remarks Dispute | RT Hr | Equipment ID Des |
| | FLUOR, A JV | ontractor: AMERICAN |
| No | R, 20-24KW DSL | 000008 GEI |
| 8.00 0.00 0.00 0.00 | 8.0 | |
| OR No | BRIS, DUST COLLECTOR | *E0080562 VAC |
| 4.00 0.00 0.00 0.00 | 4.0 | |
| No | SSOR | 000554 AIR |
| 2.00 0.00 0.00 0.00 | 2.0 | |
| No | EQUIPMENT | 000601 SAN |
| 2.00 0.00 0.00 0.00 | 2.0 | |
| 2.00 0.00 0.00 0.00 | 2.0 | |

